Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080033-7

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2961 E. COLORADO ST., PASADENA, CALIF.

No. 11357

RECEIVED FROM: PLANT #9

DATE REC'D: 2-25-57
P.O. NO.:
VENDOR PACKING SLIP NO.:

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. / S.O. NO.
	322	[illegible]D	03	D	10					

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
4	731383 Coupling Assly	5 ✓		
	IM #803112			

RECEIVED BY: [signature] HMC 106
INSPECTED BY: [signature] DATE: 2/26/57
REJECTS RETURNED ON SHIP. MEMO NO.:

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2961 E. COLORADO ST., PASADENA, CALIF.

No. 11366

RECEIVED FROM: California Rubber Products, Inc.

DATE REC'D: 2-25-57
P.O. NO.: 6822
VENDOR PACKING SLIP NO.: 352

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. / S.O. NO.
	322	000000	12886	0	0	00	00	02		

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
[illegible]	[illegible] 720155-071	25 ✓		
	To Supersede Rec. Insp. Rep. 11252			

RECEIVED BY: [signature] HMC 106
INSPECTED BY: [signature] DATE: 2/26/57
REJECTS RETURNED ON SHIP. MEMO NO.:

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080033-7